Cosmelight Plate-making Process




Expose to UV light through substrate film on back side of plate.




After wiping off the surface moisture, dry in a hot air dryer.







Peel the cover film off. Contact the emulsion side of a negative film onto plate surface.



Expose to UV light again to complete photo-curing.



Expose to UV light imagiwise through the negative film.



Remove the negative film and process the plate in Cosmolight® washout unit.



Expose to UV-C light to eliminate the tackiness of the plate surface.